



photo 1: Facing southeast toward the location. The access road passes thru the location.



photo 2: East side of the location facing west. Vegetation has not adequately established.



photo 3: View of groundcover at the east side of the location. The vegetation has not established in this area.



photo 4: There is List B noxious weeds (Diffuse knapweed) found growing throughout the location.



photo 5: There is straw debris left in piles at the west side of the location.



photo 6: Facing east along the south side of the location.



photo 7: Facing along the cut slope at the southeast side of the location.



photo 8: There is plastic debris along areas of the southeast cut slope.