



**photo 1:** Facing west along the former access road. The vegetation has not adequately established.



**photo 2:** Facing west along the former access road. The vegetation has not adequately established.



**photo 3:** Facing southwest toward the location.



**photo 4:** There areas at the location which do not have adequate vegetation cover.



**photo 5:** North side of the location facing south.



**photo 6:** Facing east toward the surrounding undisturbed reference area.