



photo 1: Facing northwest along the former access road. The vegetation has not adequately established.



photo 2: Facing northwest along the former access road. The vegetation has not adequately established.



photo 3: Facing north toward the location.



photo 4: West side of the location facing east. Vegetation has not adequately established in this area.



photo 5: Facing toward the north side of the location. Vegetation has not adequately established in this area.



photo 6: North side of the location facing south.



photo 7: Facing southwest toward the location.



photo 8: Facing southwest toward the surrounding undisturbed reference area.