

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/30/2016
Submitted Date:
11/30/2016
Document Number:
684902686

FIELD INSPECTION FORM

Loc ID 327437 Inspector Name: Pesicka, Conor On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10391
Name of Operator: STONEHAM PRODUCTION LLC
Address: 5945 ZINNIA COURT
City: ARVADA State: CO Zip: 80004

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		rbarton@sterlingenergy.us	Sterling Energy

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246899	WELL	PR	07/26/2013	GW	123-14696	CRAIG 2	PR
264214	PIT	AC	07/15/2002		-	CRAIG 2 A	AC
264215	PIT	AC	07/15/2002		-	CRAIG 2 B	AC
264216	PIT	AC	07/15/2002		-	CRAIG 2 C	AC
264217	PIT	AC	07/15/2002		-	CRAIG 2 D	AC

General Comment:

[Followup inspection to inspection doc#684902134 in response to form 42](#)

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	corrosion inhibitor		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Associated to wellhead		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	pumps - 1 corrosion inhibitor		
Corrective Action:		Date:	
Type: Veritcal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	ajax		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.718640,-103.662860
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 246899 Type: WELL API Number: 123-14696 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Bradenhead plumbed to surface

Corrective Action:

Date:

Facility ID: 264214 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 264215 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 264216 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 264217 Type: PIT API Number: - Status: AC Insp. Status: AC

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 264217 Lat: 40.717864 Long: -103.662331

Reference Point: SE Other: _____ Length: 90 Width: 25

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: Adjacent produced water

Corrective Action

Date: _____

Type: _____ Lined: _____ Pit ID: 264216 Lat: 40.718070 Long: -103.662338

Reference Point: SE Other: _____ Length: 45 Width: 25

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<u>Adjacent produced water</u>	
Corrective Action		Date:
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: <u>264214</u>
	Lat: <u>40.718197</u>	Long: <u>-103.662733</u>
Reference Point: <u>SE</u>	Other: _____	Length: <u>25</u>
		Width: <u>25</u>
Lining:		
Liner Type:	Liner Condition:	
Comment:		
Corrective Action		Date: <u>g</u>
Fencing:		
Fencing Type: <u>None</u>	Fencing Condition:	
Comment:		
Corrective Action		Date:
Netting:		
Netting Type:	Netting Condition:	
Comment:		
Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<u>Produced water pit with adjacent skim</u>	
Corrective Action		Date:
Type:	Lined:	Pit ID: <u>264215</u>
		Lat: <u>40.718055</u>
		Long: <u>-103.662626</u>
Reference Point: <u>SE</u>	Other: _____	Length: <u>30</u>
		Width: <u>30</u>
Lining:		
Liner Type:	Liner Condition:	
Comment:		
Corrective Action		Date: <u>g</u>
Fencing:		
Fencing Type:	Fencing Condition:	
Comment:		
Corrective Action		Date:
Netting:		
Netting Type:	Netting Condition:	
Comment:		
Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>

Comment:	Adjacent produced water	Date:
Corrective Action		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684902686	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4020744