

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/02/2016
Submitted Date:
12/07/2016
Document Number:
678200570

FIELD INSPECTION FORM

Loc ID 317219 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 70385
Name of Operator: SMITH ENERGY CORP
Address: 12706 SHILOH RD
City: GREELEY State: CO Zip: 80631

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Smith, Glen	(970) 386-6253	gsmithen@what-wire.com	
Benish, Erick	(970) 630-5723	Entrullc@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
104569	PIT	AC			-	BURNS 1	EI
117748	PIT	AC			-	BURNS 1	EI

General Comment:

[Environmental inspection.](#)

Inspected FacilitiesFacility ID: 104569 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 117748 Type: PIT API Number: - Status: AC Insp. Status: EI**COGCC Comments**

Comment	User	Date
Submit a Form 27 to NE EPS (rob.young@state.co.us) for the produced water impacted soils adjacent to the access road by 12/30/2016.	youngr	12/07/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678200571	View ESE from wellhead across access rd. and area of produced water impacted vegetation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4021811
678200572	View N at produced water pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4021812