

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2016

Submitted Date:

12/01/2016

Document Number:

678800153**FIELD INSPECTION FORM**
 Loc ID 437999 Inspector Name: LEONARD, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10311Name of Operator: SYNERGY RESOURCES CORPORATIONAddress: 20203 HIGHWAY 60City: PLATTEVILLE State: CO Zip: 80651**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Paddington, Dave		dpennington@syrinfo.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437997	WELL	AL	10/09/2014	LO	123-39821	SRC MARKHAM C-16-9CHZ	AL
437998	WELL	AL	10/09/2014	LO	123-39822	SRC MARKHAM C-16-9NHZ	AL
438000	WELL	AL	10/09/2014	LO	123-39823	SRC MARKHAM 31-16-9CHZ	AL
438002	WELL	AL	10/09/2014	LO	123-39825	SRC MARKHAM 31-16-9NHZ	AL
438013	WELL	AL	10/09/2014	LO	123-39834	SRC MARKHAM R-16-9NHZ	AL
438035	WELL	AL	10/09/2014	LO	123-39851	SRC MARKHAM 41-16-9NHZ	AL
438038	WELL	AL	10/09/2014	LO	123-39853	SRC MARKHAM 41-16-9CHZ	AL
438039	WELL	AL	10/09/2014	LO	123-39854	SRC MARKHAM R-16-9CHZ	AL

General Comment:

Inspected Facilities									
Facility ID:	<u>437997</u>	Type:	<u>WELL</u>	API Number:	<u>123-39821</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>437998</u>	Type:	<u>WELL</u>	API Number:	<u>123-39822</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>438000</u>	Type:	<u>WELL</u>	API Number:	<u>123-39823</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>438002</u>	Type:	<u>WELL</u>	API Number:	<u>123-39825</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>438013</u>	Type:	<u>WELL</u>	API Number:	<u>123-39834</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>438035</u>	Type:	<u>WELL</u>	API Number:	<u>123-39851</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>438038</u>	Type:	<u>WELL</u>	API Number:	<u>123-39853</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>
Facility ID:	<u>438039</u>	Type:	<u>WELL</u>	API Number:	<u>123-39854</u>	Status:	<u>AL</u>	Insp. Status:	<u>AL</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment: No evidence of construction in cultivated field

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built Pass

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation Pass Well Release on Active Location ☐ Multi-Well Location ☐

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678800153	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017255