

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2016

Submitted Date:

12/01/2016

Document Number:

685301882**FIELD INSPECTION FORM**
 Loc ID 334215 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Weems, Mark		mark.weems@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214851	WELL	PR	02/01/2011	GW	067-06455	Richardson 01-01 1	PR

General Comment:[Scheduled MIT. Witnessed by Inspector.](#)

Inspected FacilitiesFacility ID: 214851 Type: WELL API Number: 067-06455 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Well currently shut in with Key Energy workover rig on well. MIT conducted to SI well until recompletion at later date. Bridge plug was set at 5255' and 2 sxs cement placed above bridge plug. Casing filled with water and allowed to stabilize. Well was pressured up to 250 psi for approximately 6 min and then pressured up to 500 psi. Well held pressure at 500 psi for 30 min. Operator to submit completed Form 21 and chart.

Corrective Action: _____ Date: _____

WorkoverComment: Key Energy Rig on well plugging off Dakota formation.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301882	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017342
685301883	Chart 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016994
685301884	Chart 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016995
685301885	Completed Chart	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016996