

Location

Lease Road:

Type	Main				
comment:					
Corrective Action				Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD				
Comment:					
Corrective Action:				Date:	

Emergency Contact Number:

Comment:	ok				
Corrective Action:				Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD				
Comment:	1" pipe fence se corner n39.84976 w-104.35182				
Corrective Action:				Date:	

Equipment:

					corrective date
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:

Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 201405 Type: WELL API Number: 001-06808 Status: PR Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
document# 685500286, dated 8/2/16 soiled dirt cleaned up, unused equipment picked up	montoyaj	12/01/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685501514	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017360