

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/30/2016
Submitted Date:
12/01/2016
Document Number:
685301882

FIELD INSPECTION FORM

Loc ID 334215 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Weems, Mark		mark.weems@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214851	WELL	PR	02/01/2011	GW	067-06455	Richardson 01-01 1	PR

General Comment:

[Scheduled MIT. Witnessed by Inspector.](#)

Inspected Facilities

Facility ID: 214851 Type: WELL API Number: 067-06455 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well currently shut in with Key Energy workover rig on well. MIT conducted to SI well until recompletion at later date. Bridge plug was set at 5255' and 2 sxs cement placed above bridge plug. Casing filled with water and allowed to stabilize. Well was pressured up to 250 psi for approximately 6 min and then pressured up to 500 psi. Well held pressure at 500 psi for 30 min. Operator to submit completed Form 21 and chart.

Corrective Action: _____ Date: _____

Workover

Comment: Key Energy Rig on well plugging off Dakota formation.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301882	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4022010
685301883	Chart 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016994
685301884	Chart 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016995
685301885	Completed Chart	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016996