



photo 1: Facing southeast along the access road toward the location.



photo 2: Facing toward the west cut slope which has been seeded and hydro mulched.