



photo 1: Rock rip/rap has been added to area near the access road.



photo 2: Facing back to the northeast along the main road. Gravel has been applied to this area of the road.



photo 3: Facing toward the southwest side of the location.



photo 4: Facing toward the southwest side of the location.