



**photo 1:** Facing west along the main access road.



**photo 2:** The culvert along the access road is maintained.



**photo 3:** Facing southwest along the main access road. Gravel was applied and the culvert is maintained.



**photo 4:** Facing back to the northeast along the road. Erosion along the side of the road was repaired.



**photo 5:** A new culvert was installed along the road.



**photo 6:** Facing southwest toward the location. The cut slope has been seeded and hydromulched.