



photo 1: Facing west along the main access road. A new culvert has been installed along the road and gravel has been applied.



photo 2: Facing west along the main access road. A new culvert has been installed along the road and gravel has been applied.



photo 3: Facing toward the northwest cut slope which was seeded and hydro-mulched.