



**photo 1:** Facing west along the main access road. The culverts are maintained.



**photo 2:** Facing west toward the location.