



**Inspected Facilities**

Facility ID: 251280 Type: WELL API Number: 123-19083 Status: DA Insp. Status: DA

**Cement**

Cement Contractor

Contractor Name: \_\_\_\_\_

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment: ENSIGN 313 ON LOCATION RIGGING UP TO RE-ENTER TO RE-PLUG WELL. CASING HAS BEEN EXTENDED.

Corrective Action:

Date: \_\_\_\_\_

**BradenHead**

Comment: No Bradenhead.

Corrective Action:

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681901835	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4019121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4019121</a>