

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2016

Submitted Date:

12/12/2016

Document Number:

672500237**FIELD INSPECTION FORM**
 Loc ID 409322 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 93200Name of Operator: VESSELS OIL & GAS COMPANYAddress: 8435 W 88TH AVECity: ARVADA State: CO Zip: 80005**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	
Kulmann, Dave		dave.kulmann@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.u s	
Mah, Steven		steven.mah@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251280	WELL	DA	03/31/1996	DA	123-19083	ERIE CHAMPLIN 18-9	DA

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare	
Comment:	ENCLOSED NOT IN USE AT TIME OF INSPECTION	
Corrective Action:		Date:

Inspected Facilities

Facility ID: 251280 Type: WELL API Number: 123-19083 Status: DA Insp. Status: DA

Complaint

Comment: [Complaint #: 200440687/200440686/200440679/200440685/200440689](#)

[Field Inspector Assigned: Jason E. Gomez](#)

[Complaint Received:](#)

[Date: 12-12-2016 Time 0730 Hrs](#)

[Contacted by Inspector:](#)

[Date: Time Hrs](#)

[Well Number#: 05-123-19083 Location #: 409322](#)

[Inspection Document #: 672500237](#)

[Complainant: Vallee Johnson Phone:](#)

[Address: 325 Anderson CT, Erie Co 80516](#)

[Nature of complaint: Noise/Lighting/Odor](#)

[Field Inspector Actions:](#)

[On 12-12-2016, I was contacted by Dave Kulman Deputy Director of the COGCC in reference to a complaint at the residence of the complainant Vallee Johnson 325 Anderson Ct, Erie Colorado.](#)

[The complaint indicated in her complaint she was experiencing noise, odor and lighting issues coming from the Erie Champlin 18-9 location. The complainant indicated a whirring noise was coming from the location and she had experienced a strong smell coming from location as well as at night time the lights from location were shining into her home.](#)

[I performed a complete site inspection at locations. At the time of inspection, I observed an Ensign pulling unit performing a re-entry operation at the location under the direction of Crestone operations. During my inspection I observed approx. 4 light stands at location with several of the lights point up toward the derrick of the rig. At the time of the inspection the lights were not in use.](#)

[I also performed a sound study to the south of the location toward the complainant's home approx. 350' from the source of the sound on location. See inspection Doc #672500237 for attached photos of lighting at location and attached sound study and thermal imagery of location for VOC's. At the time of inspection no odor issues were detected and no VOC's were visible in thermal imagery. The potential Odor issues stated in this complaint were turned over to CDPHE for further investigation.](#)

[At the time of inspection, I observed a potential violation of rule 803 of COGCC rules which were indicated in the complaints.](#)

[I Contacted Crestone personnel Tarah Garza and notified her of inspections issues with BMP's, I also spoke with Kelvin Edsall consultant for Crestone and advised him of the complaints and the light issues I observed on location. Both parties I contacted indicated they would attempt to get the issues resolved ASAP.](#)

Corrective Action: **"Comply with the lighting requirements in Rule 803."**

Date: 12/13/2016

Workover

Comment: RE-ENTRY DRILL OUT IN PROCCSS

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Silt Fences	Fail			Material Handling And Spill Prevention	Pass	
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	

Comment: [BMP not properly maintained](#)

Corrective Action: "Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details."

Date: 12/14/2016

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☐ Production ☒ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.049580 Long: -104.039920Wind: Light Speed: 2-5 (mph) Direction From: NW Weather: Partly Temperature: 32 (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☒ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
1533	PM	1555	PM	Other

Comment: VIEWED WOROVER DRILL OUT OF RE-RENTRY

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
672500238	Generators with Lights pointed up toward the Rig Derrick	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025318
672500239	Generators with lights pointed up toward the Rig Derrick	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025319
672500240	Silt Fence	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025320
672500241	Silt Fence	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025321
672500242	Silt Fence	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025322
672500243	Silt Fence	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025323
672500244	SOUND STUDY	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025324
672500245	THERMAL IMAGERY	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025325