

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/12/2016
Submitted Date:
12/12/2016
Document Number:
685301955

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312035 _____ St John, William (Cal) _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

- 18 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274149	WELL	PR	10/15/2004	GW	067-08983	SEMLER A 2	PR
292313	WELL	PR	09/18/2007	GW	067-09395	SEMLER A 4	PR

General Comment:

Inspection report contains corrective action and comments. See Signs/Marker, Good housekeeping, and Storm Water Sections of report for additional details. See Link at end of report for path to downloadable pictures.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign is broken off base. Information for Semler A 4 is peeling and unreadable. Inspector leaned sign up against fence.		
Corrective Action:	Install sign to comply with Rule 210.b		Date: 02/11/2017

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Disconnected section of piping left at A 2 wellhead.		
Corrective Action:	Remove pipe to comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 01/12/2017
Type	UNUSED EQUIPMENT		
Comment:	Concrete block with metal base left on the W side of location.		
Corrective Action:	Remove concrete block to comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 01/12/2017

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Steel Mesh Safety Barrier		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Post and Wire.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Panel - Includes Gas Meter Run and Produced Water Tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Panel		

Corrective Action:				Date:	
Equipment:					corrective date
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Flow Line	# 2				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment: Electric Motor					
Corrective Action:				Date:	
Type: Vertical Heated Separator	# 1				
Comment: Single Steel Building with Two Separators.					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment: Electrical Service Equipment					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment: Telemetry Equipment					
Corrective Action:				Date:	
Type: Gas Meter Run	# 2				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment: Wellhead					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity) 95 BBLs	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:

Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 274149 Type: WELL API Number: 067-08983 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 292313 Type: WELL API Number: 067-09395 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					
Gravel	Pass	Gravel	Pass			
Compaction	Fail	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: [Waddles along S side of location require maintenance. Erosion channel developing on the S Side of location.](#)

Corrective Action: [Repair or install BMPs as required by Rule 1002.f. Refer to 1002.f guidance document for further details.](#)

Date: 01/12/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301964	Wellhead Sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025376
685301965	Disconnected pipe	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025377
685301966	Concrete block	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025378
685301967	Damaged waddles	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025379
685301968	Unstaked waddle	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025380
685301969	Erosion Channel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025381