

# Final Reclamation & Stormwater Inspection

12/13/2016

Operator: Petro-Canada #72085

Location ID: 311664

Adams County, CO

SWNW Section 24 T3S R59W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



**Figure 1:** Photo of GPS confirming location. See photos from inspection Doc. # 682500938 for additional information and details





2016/12/13 10:31

N39.777608 W103.940702

**Figure 2:** Photo taken west (down slope) of the fenced remediation area, facing east. Photo shows large unvegetated areas . Refer to photos from inspection Doc. # 682500938 for additional details.





**Figure 3:** : Photo taken west (down slope) of the fenced remediation area, facing east. Photo shows large unvegetated areas . Refer to photos from inspection Doc. # 682500938 for additional details.





2016/12/13 10:35

N39.778790 W103.941242

**Figure 4:** Photo taken from the northern disturbance area, facing east towards the access road. Photo shows erosion has not been stabilized. Refer to photos from inspection Doc. # 682500938 for additional details.





2016/12/13 10:36

N39.778792 W103.940933

**Figure 5:** Photo taken from the northern disturbance area, facing east towards the access road. Photo shows erosion has not been stabilized or reclaimed. Refer to photos from inspection Doc. # 682500938 for additional details.





2016/12/13 10:36

N39.778793 W103.940935

**Figure 6:** Photo taken from the northern disturbance area, facing east towards the access road. Photo shows erosion has not been stabilized or reclaimed. Refer to photos from inspection Doc. # 682500938 for additional details.





2016/12/13 10:36

N39.778810 W103.940643

**Figure 7:** Photo taken from the northern disturbance area, facing east towards the access road. Photo shows erosion has not been stabilized or reclaimed. Refer to photos from inspection Doc. # 682500938 for additional details.





2016/12/13 10:37

N39.778965 W103.940508

**Figure 8:** Photo taken from the northern disturbance area, facing east towards the access road. Photo shows erosion has not been stabilized or reclaimed. Refer to photos from inspection Doc. # 682500938 for additional details.