



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing westward.





Photo 3. View of stormwater controls in the southern portion of the project area. Appear to be functioning at this time but will soon need maintenance.





Photo 4. View of more stormwater controls in the southern portion of the project area. Appear to be functioning at this time but will soon need maintenance.