



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Interim reclamation areas are revegetating with desirable species such as western wheatgrass (*Pascopyrum smithii*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).





Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward.





Photo 4. View of the southeastern portion of the project area from the southeastern edge facing eastward.





Photo 5. View of cobble run-down in the southwestern corner of the project area appears to be functioning at this time.





Photo 6. View of erosional channel near the entrance to the well pad.