

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2016

Submitted Date:

12/08/2016

Document Number:

680601143**FIELD INSPECTION FORM**
 Loc ID 326578 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 19160Name of Operator: CONOCO PHILLIPS COMPANYAddress: P O BOX 2197City: HOUSTON State: TX Zip: 77252-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|-----------------------------------|--------------------|
| Notor, Lori | | Lori.R.Notor@conocophillips.com | SW Inspections |
| Walker, Crystal | | Crystal.Walker@conocophillips.com | All Inspections |
| Busse, Dollie | 505-324-6104 | Dollie.L.Busse@conocophillips.com | All SW Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 258229 | WELL | PR | 02/24/2001 | GW | 067-08339 | ARGENTA 33-10 4-4 | RI |

General Comment:

This is an interim reclamation and stormwater inspection. Stormwater controls recently installed along a nearby segment of La Posta Canyon Road were also assessed.

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 258229 | Type: | WELL | API Number: | 067-08339 | Status: | PR | Insp. Status: | RI |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by mixed pinion juniper woodland. Revegetation is progressing within the interim reclamation areas along with significant ruderal weedy cover.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? FailComment Guy line anchors are not marked.Corrective Action Mark or remove guy line anchors.Date **01/13/2017**

| | |
|--|--|
| 1003b. Area no longer in use? In _____ 1003c. Compacted areas have been cross ripped? _____ 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____ Cuttings management: _____ 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In _____ Production areas have been stabilized? _____ Segregated soils have been replaced? _____ | |
|--|--|

RESTORATION AND REVEGETATION

Cropland

| | | |
|-------------------------|-------------------|---------------------------------------|
| Top soil replaced _____ | Recontoured _____ | Perennial forage re-established _____ |
|-------------------------|-------------------|---------------------------------------|

Non-Cropland

| | | |
|-------------------------|-------------------|------------------------------|
| Top soil replaced _____ | Recontoured _____ | 80% Revegetation In _____ |
|-------------------------|-------------------|------------------------------|

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? I _____

Comment Scattered musk thistle rosettes were observed within the interim reclamation area. Weeds will need to be controlled before seedhead maturity in 2017.

Corrective Action Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

| | | |
|---|---|------------------------|
| Well plugged _____ | Pit mouse/rat holes, cellars backfilled _____ | |
| Debris removed _____ | No disturbance /Location never built _____ | |
| Access Roads Regraded _____ | Contoured _____ | Culverts removed _____ |
| Gravel removed _____ | | |
| Location and associated production facilities reclaimed _____ | Locations, facilities, roads, recontoured _____ | |
| Compaction alleviation _____ | Dust and erosion control _____ | |
| Non cropland: Revegetated 80% _____ | Cropland: perennial forage _____ | |
| Weeds present _____ | Subsidence _____ | |

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |
| <p>Comment: Rilling is occurring along the edges of the working area and facilities. This needs to be monitored and stormwater controls applied if necessary. Stormwater controls recently installed along a segment of La Posta Canyon Road appear to be functioning an in good condition. See attached photos.</p> <p>Corrective Action: Date: _____</p> <p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p> | | | | | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 680601143 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027913 |
| 680601144 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4022704 |