



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Interim reclamation areas are revegetating with desirable species such as smooth brome (*Bromus inermis*), false goldenaster (*Heterotheca villosa*), and dropseed (*Sporobolus* sp.).





Photo 3. View of the western portion of the project area from the southwestern corner facing northward.





Photo 4. View of cobble armouring along well pad entrance and access ramp appears to be functioning.





Photo 5. View of the eastern portion of the project area from the southeastern corner facing northward.





Photo 6. View of northern portion of the project area from the northeastern edge facing westward.