

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
12/09/2016  
Submitted Date:  
12/09/2016  
Document Number:  
674103870

**FIELD INSPECTION FORM**

Loc ID 438758 Inspector Name: Rickard, Jeff On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
OGCC Operator Number: 10311  
Name of Operator: SYNERGY RESOURCES CORPORATION  
Address: 20203 HIGHWAY 60  
City: PLATTEVILLE State: CO Zip: 80651

**Contact Information:**

Contact Name	Phone	Email	Comment
Pennington, Dave		dpennington@syrginfo.com	Synergy Inspection

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438755	WELL	PR	12/01/2015	LO	123-40110	SRC Wind M-17N-A	PR
438756	WELL	PR	12/01/2015	LO	123-40111	SRC Wind E-17N-C	PR
438757	WELL	PR	12/01/2015	LO	123-40112	SRC Wind 21-17C	PR
438759	WELL	PR	12/01/2015	LO	123-40113	SRC Wind A-17N-C	PR
438760	WELL	PR	12/01/2015	LO	123-40114	SRC Wind A-17N-A	PR
438761	WELL	PR	12/01/2015	LO	123-40115	SRC Wind 21-17N-C	PR
438762	WELL	PR	12/01/2015	LO	123-40116	SRC Wind 11-17C	PR
439255	WELL	PR	12/01/2015	LO	123-40372	SRC Wind 11-17N-C	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type		#		corrective date
Type: Gas Meter Run		# 1		
Comment:	<input type="text"/>			
Corrective Action:				Date:
Type: Plunger Lift		# 8		
Comment:	<input type="text"/>			
Corrective Action:				Date:
Type: Compressor		# 2		
Comment:	<input type="text"/>			
Corrective Action:				Date:
Type: VRT		# 2		
Comment:	<input type="text"/>			
Corrective Action:				Date:
Type: Emission Control Device		# 6		
Comment:	<input type="text"/>			
Corrective Action:				Date:
Type: Horizontal Heated Separator		# 8		
Comment:	<input type="text"/>			
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:	<input type="text"/>				
Corrective Action:					Date:

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>

Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	10	400 BBLs	STEEL AST		40.306930,-104.917290	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No						
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities			
Facility ID:	438755	Type:	WELL
API Number:	123-40110	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	
<b>BradenHead</b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID:	438756	Type:	WELL
API Number:	123-40111	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	
<b>BradenHead</b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID:	438757	Type:	WELL
API Number:	123-40112	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	
<b>BradenHead</b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID:	438759	Type:	WELL
API Number:	123-40113	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	
<b>BradenHead</b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID:	438760	Type:	WELL
API Number:	123-40114	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

<b>BradenHead</b>		
Comment:	<input type="text" value="Braden head is exposed at surface."/>	Date: _____
Corrective Action:	<input type="text"/>	

Facility ID: 438761 Type: WELL API Number: 123-40115 Status: PR Insp. Status: PR

<b>Producing Well</b>		
Comment:	<input type="text" value="PR"/>	Date: _____
Corrective Action:	<input type="text"/>	

<b>BradenHead</b>		
Comment:	<input type="text" value="Braden head is exposed at surface."/>	Date: _____
Corrective Action:	<input type="text"/>	

Facility ID: 438762 Type: WELL API Number: 123-40116 Status: PR Insp. Status: PR

<b>Producing Well</b>		
Comment:	<input type="text" value="PR"/>	Date: _____
Corrective Action:	<input type="text"/>	

<b>BradenHead</b>		
Comment:	<input type="text" value="Braden head is exposed at surface."/>	Date: _____
Corrective Action:	<input type="text"/>	

Facility ID: 439255 Type: WELL API Number: 123-40372 Status: PR Insp. Status: PR

<b>Producing Well</b>		
Comment:	<input type="text" value="PR"/>	Date: _____
Corrective Action:	<input type="text"/>	

<b>BradenHead</b>		
Comment:	<input type="text" value="Braden head is exposed at surface."/>	Date: _____
Corrective Action:	<input type="text"/>	

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: DRY LAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use?  In  Production areas stabilized ?  In

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed?  Subsidence over on drill pit?

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized?  Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced  Recontoured  Perennial forage re-established

Non-Cropland

Top soil replaced  Recontoured  80% Revegetation

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA%

TRANSECT RESULTS OF REFERENCE AREA%

TOTAL % OF DESIRABLE VEGETATION COVER

VEGETATIVE COVER

1003 f. Weeds Noxious weeds?

Comment

Corrective Action

Date

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started:  Date Final Reclamation Completed:

Final Land Use: DRY LAND

Reminder:

Comment:

Well plugged  Pit mouse/rat holes, cellars backfilled

Debris removed  No disturbance /Location never built

Access Roads  Regraded  Contoured  Culverts removed

Gravel removed

Location and associated production facilities reclaimed  Locations, facilities, roads, recontoured

Compaction alleviation  Dust and erosion control

Non cropland: Revegetated 80%  Cropland: perennial forage

Weeds present  Subsidence

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA%

TRANSECT RESULTS OF REFERENCE AREA%

TOTAL % OF DESIRABLE VEGETATION COVER

VEGETATIVE COVER

Comment:

Corrective Action:

Date

Overall Final Reclamation  Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674103870	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4029046">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4029046</a>