



Photo#1: View of Location from Road opposite to SE.



Photo#2: Overview of Location to North.

Inspection Photos: Laramie Energy Cascade Creek Loc#423240



November 14, 2016



## Revegetation of Fill Slopes is Unsuccessful

Photo#3:

Photo #4



November 14, 2016

Inspection Photos: Laramie Energy Cascade  
Creek Loc#423240



Vegetation is establishing in a few areas  
Photo#5:



Photo:6:



November 14, 2016

Inspection Photos: Laramie Energy Cascade  
Creek Loc#423240





Photo#7: Erosion occurring on Fill Slope.

Inspection Photos: Laramie Energy Cascade Creek Loc#423240

November 14, 2016