

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2016

Submitted Date:

12/09/2016

Document Number:

673503927**FIELD INSPECTION FORM**
 Loc ID 309123 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|---------------------------|-------------------------------|---------|
| Begano, Mary | 719-859-1918/719-846-2102 | mary_begano@xtoenergy.com | |
| Harrison, Lyndon | | lyndon_harrison@xtoenergy.com | |
| Trujillo, Irwin | | irwin_trujillo@xtoenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 288298 | WELL | PR | 06/04/2007 | GW | 071-09112 | GOLDEN EAGLE 29-6 | RI |
| 292688 | PIT | AC | 09/03/2008 | | - | GOLDEN EAGLE 29-06 | AC |

General Comment:

This is an Interim Reclamation and Stormwater Management Inspection.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

| | |
|--|---|
| Date Final Reclamation Started: _____ | Date Final Reclamation Completed: _____ |
| Final Land Use: _____ | |
| Reminder: _____ | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| Well plugged _____ | Pit mouse/rat holes, cellars backfilled _____ |
| Debris removed _____ | No disturbance /Location never built _____ |
| Access Roads _____ | Regraded _____ Contoured _____ Culverts removed _____ |
| Gravel removed _____ | |
| Location and associated production facilities reclaimed _____ | Locations, facilities, roads, recontoured _____ |
| Compaction alleviation _____ | Dust and erosion control _____ |
| Non cropland: Revegetated 80% _____ | Cropland: perennial forage _____ |
| Weeds present _____ | Subsidence _____ |
| 1004.d. FINAL VEGETATION TRANSECT | |
| TRANSECT RESULTS OF DISTURBED AREA% _____ | |
| TRANSECT RESULTS OF REFERENCE AREA% _____ | |
| TOTAL % OF DESIRABLE VEGETATION COVER _____ | |
| VEGETATIVE COVER _____ | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| Overall Final Reclamation _____ | Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Hydro Mulch | Pass | Gravel | Pass | | | |
| Rip Rap | Pass | Rip Rap | Pass | | | |

Comment: [Areas of erosion accross and along the road have been repaired. Bmps are installed along the road. See Attached Photos](#)

Corrective Action: Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: 292688 Lat: 37.144790 Long: -104.913500

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition: Adequate

Comment:

Corrective Action: Date: g

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action: Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action: Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard:

Comment:

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 673503927 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4024851 |
| 673503928 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4024561 |