

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
12/12/2016  
Submitted Date:  
12/12/2016  
Document Number:  
685301955

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: St John, William (Cal) On-Site Inspection   
312035 \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

**Findings:**

- 18 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274149	WELL	PR	10/15/2004	GW	067-08983	SEMLER A 2	PR
292313	WELL	PR	09/18/2007	GW	067-09395	SEMLER A 4	PR

**General Comment:**

Inspection report contains corrective action and comments. See Signs/Marker, Good housekeeping, and Storm Water Sections of report for additional details. See Link at end of report for path to downloadable pictures.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign is broken off base. Information for Semler A 4 is peeling and unreadable. Inspector leaned sign up against fence.		
Corrective Action:	Install sign to comply with Rule 210.b		Date: 02/11/2017

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Concrete block with metal base left on the W side of location.		
Corrective Action:	Remove concrete block to comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 01/12/2017
Type	UNUSED EQUIPMENT		
Comment:	Disconnected section of piping left at A 2 wellhead.		
Corrective Action:	Remove pipe to comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 01/12/2017

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Panel - Includes Gas Meter Run and Produced Water Tank.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Steel Mesh Safety Barrier		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Post and Wire.		

Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment: <a href="#">Electric Motor</a>			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: <a href="#">Telemetry Equipment</a>			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment: <a href="#">Single Steel Building with Two Separators.</a>			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: <a href="#">Electrical Service Equipment</a>			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment: <a href="#">Wellhead</a>			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity) 95 BBLs	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 274149 Type: WELL API Number: 067-08983 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

Facility ID: 292313 Type: WELL API Number: 067-09395 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					
Gravel	Pass	Gravel	Pass			
Compaction	Fail	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: Waddles along S side of location require maintenance. Erosion channel developing on the S Side of location.

Corrective Action: Repair or install BMPs as required by Rule 1002.f. Refer to 1002.f guidance document for further details.

Date: 01/12/2017

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301955	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025388">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025388</a>
685301964	Wellhead Sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025376">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025376</a>
685301965	Disconnected pipe	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025377">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025377</a>
685301966	Concrete block	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025378">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025378</a>
685301967	Damaged waddles	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025379">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025379</a>
685301968	Unstaked waddle	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025380">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025380</a>
685301969	Erosion Channel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025381">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025381</a>