

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2016

Submitted Date:

12/14/2016

Document Number:

672500258**FIELD INSPECTION FORM**
 Loc ID 409322 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 93200Name of Operator: VESSELS OIL & GAS COMPANYAddress: 8435 W 88TH AVECity: ARVADA State: CO Zip: 80005**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		Cogcc.inspections@crestonepr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251280	WELL	DA	03/31/1996	DA	123-19083	ERIE CHAMPLIN 18-9	DA

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

**Flaring:**

Type	Field Flare	
Comment:	ENCLOSED NOT IN USE AT TIME OF INSPECTION	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 251280 Type: WELL API Number: 123-19083 Status: DA Insp. Status: DA

**Complaint**

Comment: [Complaint #: 200440714](#)

[Field Inspector Assigned: Jason E. Gomez](#)

[Complaint Received:](#)

[Date: 12-13-2016 Time 2100 Hrs](#)

[Contacted by Inspector:](#)

[Date: Time 12-14-2016 1430 Hrs](#)

[Well Number#: 05-123-19083 Location #: 409322](#)

[Inspection Document #: 672500258](#)

[Complainant: Darren Champion Phone: 303-482-1734](#)

[Address: 484 Main St Erie Co 80516](#)

[Nature of complaint: Lighting](#)

[Field Inspector Actions:](#)

[On 12-14-2016, I was contacted by Dave Kulman Deputy Director of the COGCC in reference to a complaint at the residence of the complainant Darren Champion at 428 Main St in Erie Colorado.](#)

[The complaint indicated in his complaint he was experiencing bright lights coming from the Erie Champlin 18-9 location. Upon speaking with him he said the lights were bothering him on his drive home in the evenings.](#)

[I performed a complete site inspection at locations. At the time of inspection all light appeared to be pointed toward the ground and toward the center of the location per COGCC rules. At the time of the inspection the lights were not in use. See inspection Doc #672500258 for attached photos of lighting at location.](#)

[At the time of inspection, I no violations of COGCC rules were observed.](#)

Corrective Action:

Date:

**Workover**

Comment: [RE-ENTRY DRILL OUT ALL LIGHT WERE POINTED DOWN TOWRD THE GROUND AND CENTER OF LOCATION AT TIME OF INSPECTION SEE ATTACHED PHOTO](#)

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
672500259	LIGHTS APPEAR TO BE IN COMPLIANCE	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031231">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031231</a>