

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2016

Submitted Date:

12/13/2016

Document Number:

675203667**FIELD INSPECTION FORM**

Loc ID 440634 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Bleil, Rob	(970) 329-4373	rbleil@ursaresources.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Knudson, Dwayne	(970) 456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440641	WELL	XX	09/19/2016	LO	045-22713	B&V 11A-18-07-95	XX

General Comment:[Inspection in response to complaint Doc#200440625. Lighting in question has been taken down.](#)

Inspected FacilitiesFacility ID: 440641 Type: WELL API Number: 045-22713 Status: XX Insp. Status: XX**Complaint**Comment: [Inspection in response to complaint Doc#200440625. Lighting in question has been taken down.](#)

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203667	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4025681