

Location

Overall Good:

Signs/Marker:

Type			
Comment:			
Corrective Action:		Date:	01/13/2017

Emergency Contact Number:

Comment: Sign not posted or information inaccurate

Corrective Action: Install sign to comply with Rule 210.b.

Date: _____

Overall Good:

Spills:

Type	Area	Volume			
Condensate	WELLHEAD	>= 5 bbls			
Comment:	Gas and condensate venting from well head. Operator installed bull plugs by the end of the day on 12/9				
Corrective Action:	Contact Cogcc Enviromental staff to report spill.			Date:	12/15/2016

In Containment: No

Comment: _____

Multiple Spills and Releases?

Venting:

Yes/No	YES		
Comment:	Well head was venting at the time of inspection. Bull plug was installed by the end of the day on 12/9. Cogcc engineering staff was notified by BLM staff on 12/8 of venting.		
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680200054	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4026251