

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2016

Submitted Date:

12/14/2016

Document Number:

682401613**FIELD INSPECTION FORM**
 Loc ID 421847 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445241	WELL	XX	03/29/2016		123-42968	Magpul Federal LC21-675	CI
445242	WELL	XX	03/29/2016		123-42969	Mossberg Federal LC10-765	CI
445243	WELL	XX	03/29/2016		123-42970	Diamondback Federal LC22-770	CI
445244	WELL	XX	03/29/2016		123-42971	Magpul Federal LC21-670	CI
445245	WELL	XX	03/29/2016		123-42972	Rattlesnake Federal LC10-785	CI
445246	WELL	XX	03/29/2016		123-42973	Benelli Federal LC22-755	CI
445247	WELL	XX	03/29/2016		123-42974	Magpul Federal LC21-680	CI
445248	WELL	XX	03/29/2016		123-42975	Benelli Federal LC22-765	CI
445249	WELL	AL	10/06/2016		123-42976	Diamondback Federal LC22-775	CI
445250	WELL	XX	03/29/2016		123-42977	Benelli Federal LC22-760	CI
445251	WELL	XX	03/29/2016		123-42978	Mossberg Federal LC10-760	CI
445252	WELL	XX	03/29/2016		123-42979	Rattlesnake Federal LC10-770	CI

**General Comment:**

This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401163473.

**Location Construction**

Location ID: 421847 CDP: \_\_\_\_\_

Comment: This inspection is for the northern pad. Additional inspections will proceed as location is completed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	Yes		

Comments: Erosion BMPs: Surface roughening, which is a temporary BMP, was installed prior to construction activities.

Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: Refer to attached inspection photos in Document #682401614.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**

Facility ID: <u>445241</u>	Type: <u>WELL</u>	API Number: <u>123-42968</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445242</u>	Type: <u>WELL</u>	API Number: <u>123-42969</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445243</u>	Type: <u>WELL</u>	API Number: <u>123-42970</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445244</u>	Type: <u>WELL</u>	API Number: <u>123-42971</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445245</u>	Type: <u>WELL</u>	API Number: <u>123-42972</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445246</u>	Type: <u>WELL</u>	API Number: <u>123-42973</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445247</u>	Type: <u>WELL</u>	API Number: <u>123-42974</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445248</u>	Type: <u>WELL</u>	API Number: <u>123-42975</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445249</u>	Type: <u>WELL</u>	API Number: <u>123-42976</u>	Status: <u>AL</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445250</u>	Type: <u>WELL</u>	API Number: <u>123-42977</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445251</u>	Type: <u>WELL</u>	API Number: <u>123-42978</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445252</u>	Type: <u>WELL</u>	API Number: <u>123-42979</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401613	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027767">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027767</a>
682401614	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027732">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027732</a>