



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Interim reclamation areas are revegetating with desirable species such as smooth brome (*Bromus inermis*), intermediate wheatgrass (*Thinopyron intermedium*), and dropseed (*Sporobolus* sp.).





Photo 3. View of the western portion of the project area from the southwestern corner facing northward.





Photo 4. View stormwater erosion in the western portion of the project area that needs to be repaired.





Photo 5. Another view of stormwater erosion in the western portion of the project area that needs to be repaired.





Photo 6. View of musk thistles (*Carduus nutans*) in the southern portion of the project area.





Photo 7. Another view of musk thistles within the project area.