



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward. It appears surface owner is storing materials along the outer edges of the project area.



Photo 4. View of the southern portion of the project area facing westward. Wetland vegetation is growing around the perimeter of the project area.