

Construction and Stormwater Inspection



Photo 1. Photo taken from the entrance of location, facing South. Vehicle tracking pad installed at entrance to mitigate sediment discharge offsite.

Construction and Stormwater Inspection



Photo 2. Photo taken from the southern location, facing West. Ditch and berm BMP installed around the perimeter of the location.

Construction and Stormwater Inspection



Photo 3. Photo taken from the western location, facing North, along the topsoil stockpile. Ditch and berm BMP installed around the perimeter of the location.

Construction and Stormwater Inspection



Photo 4. Photo taken from the northern location, facing East. Ditch and berm BMP installed around the perimeter of the location.

Construction and Stormwater Inspection



Photo 5. Photo taken from the northeastern location, facing East. Ditch and berm BMP installed around the perimeter of the location.

Construction and Stormwater Inspection



Photo 6. Photo taken from the eastern location, facing South. Ditch and berm BMP installed around the perimeter of the location.