

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2016

Submitted Date:

12/21/2016

Document Number:

682401618**FIELD INSPECTION FORM**

Loc ID 444964 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444953	WELL	DG	11/18/2016		123-42823	Dunn 7I-321	RI
444954	WELL	XX	02/27/2016		123-42824	Dunn 7Q-341	RI
444955	WELL	XX	02/27/2016		123-42825	Dunn 7L-301	RI
444956	WELL	XX	02/27/2016		123-42826	Dunn 7Q-241	RI
444957	WELL	XX	02/27/2016		123-42827	Dunn 7L-221	RI
444958	WELL	DG	11/07/2016		123-42828	Dunn 7I-201	RI
444959	WELL	XX	02/27/2016		123-42829	Dunn 7Q-301	RI
444960	WELL	XX	02/27/2016		123-42830	Dunn 7L-201	RI
444961	WELL	XX	02/27/2016		123-42831	Dunn 7Q-221	RI
444962	WELL	DG	10/27/2016		123-42832	Dunn 7L-341	RI
444963	WELL	DG	12/03/2016		123-42833	Dunn 7I-221	RI

**General Comment:**

This is a stormwater inspection in response to Form 42- Notice of construction- Document #401115154.

### Location Construction

Location ID: 444964 CDP: \_\_\_\_\_

Comment: Topsoil has been salvaged and stored along the western perimeter of location. Topsoil shall be stabilized and protected from degradation due to wind and water erosion. BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### Form 2A COAs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### Wildlife BMPs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

Inspected Facilities				
Facility ID: <u>444953</u>	Type: <u>WELL</u>	API Number: <u>123-42823</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444954</u>	Type: <u>WELL</u>	API Number: <u>123-42824</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444955</u>	Type: <u>WELL</u>	API Number: <u>123-42825</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444956</u>	Type: <u>WELL</u>	API Number: <u>123-42826</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444957</u>	Type: <u>WELL</u>	API Number: <u>123-42827</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444958</u>	Type: <u>WELL</u>	API Number: <u>123-42828</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444959</u>	Type: <u>WELL</u>	API Number: <u>123-42829</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444960</u>	Type: <u>WELL</u>	API Number: <u>123-42830</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444961</u>	Type: <u>WELL</u>	API Number: <u>123-42831</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444962</u>	Type: <u>WELL</u>	API Number: <u>123-42832</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444963</u>	Type: <u>WELL</u>	API Number: <u>123-42833</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Tracking Pad	Pass					
Ditches	Pass					
Berms	Pass					

Comment: [Ditch and berm BMP installed around perimeter of location. Did not observe a stabilized outlet to control sediment-laden stormwater from leaving location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to attached inspection photos in Document #682401629.</a>	binschusc	12/21/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401629	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4034826">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4034826</a>