

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/15/2016
Submitted Date:
12/16/2016
Document Number:
675203691

FIELD INSPECTION FORM

Loc ID 334769 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237	WELL	PR	01/15/2009	GW	045-15455	FEDERAL GARDNER 21-13BB (PK-21)	PR
238	WELL	PR	01/14/2009	GW	045-15456	FEDERAL SMITH 21-12 (PK-21)	PR
239	WELL	PR	10/14/2009	GW	045-15457	FEDERAL SMITH 21-12BB (PK-21)	PR
240	WELL	PR	09/01/2008	GW	045-15458	FEDERAL 21-11(PK-21)	PR
241	WELL	PR	01/17/2009	GW	045-15459	FEDERAL 21-11BB (PK-21)	PR
294	WELL	PR	09/01/2009	GW	045-15475	FEDERAL 21-15BB(PK-21)	PR
295	WELL	PR	08/30/2009	GW	045-15476	FEDERAL 21-10BB(PK-21)	PR
296	WELL	PR	08/28/2009	GW	045-15477	FEDERAL 21-10(PK-21)	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition Adequate

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 237 Type: WELL API Number: 045-15455 Status: PR Insp. Status: PR

Facility ID: 238 Type: WELL API Number: 045-15456 Status: PR Insp. Status: PR

Facility ID: 239 Type: WELL API Number: 045-15457 Status: PR Insp. Status: PR

Facility ID: 240 Type: WELL API Number: 045-15458 Status: PR Insp. Status: PR

Facility ID: 241 Type: WELL API Number: 045-15459 Status: PR Insp. Status: PR

Facility ID: 294 Type: WELL API Number: 045-15475 Status: PR Insp. Status: PR

Facility ID: 295 Type: WELL API Number: 045-15476 Status: PR Insp. Status: PR

Facility ID: 296 Type: WELL API Number: 045-15477 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Berms	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203691	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4029791