

Inspector Name:

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109**FIELD INSPECTION FORM**

Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 8 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
	LUJAN, CARLOS	2A Doc Num:		

Operator Information:

OGCC Operator Number: 10442

Name of Operator: HUNTER RIDGE ENERGY SERVICES LLC

Address: 370 17TH STREET #1700

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Middleton, Brett		Brett.Middleton@encana.com	Environmental Specialist
Kasten, Matt		Matthew.Kasten@encana.com	Environmental
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW
Rider, Lindsey		Lindsey.Rider@encana.com	Manager, Field Environmental
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region

General Comment:

On October 5, 6, and 11, COGCC staff conducted site inspections during a monitoring wells drilling operation. On site with Brett Middleton from Encana/Hunter Ridge; Wesley Toews and Dustin Held from LTE. (see REM #9748) The drilling operation was conducted to complete the Phase III Environmental Assessment, document submitted to the COGCC on 10/06/2016 (doc #401125566). A rotasonic drilling rig was used to improve core sampling recovery and well construction. Poorly cemented sandstone was encountered mostly on monitoring wells on both sides (east and west) of the valley. Clayey soil was encountered on monitoring well MW13 in the valley, on the east side of the creek. LTE personel developed wells drilled few days before. Photos (attached) show free product recovery during bailing operation at the MW-20 monitoring well.

COGCC Comments

Comment	User	Date
Encana / Hunter Ridge continues with Site Investigation and spill control. More Monitoring wells will be installed during the next few days (See REM #9748)	lujanc	12/19/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
671000483	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031503
671000494	Photo Report Encana A27 Oct 5-11 2016	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4031471



Inspection Date:

10/11/2016

Submitted Date:

12/19/2016

Document Number:

671000483