



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Interim reclamation areas are revegetating with desirable species such as smooth brome (*Bromus inermis*), western wheatgrass (*Pascopyrum smithii*), and dropseed (*Sporobolus* sp.).



Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4. View of the northern portion of the project area from the northwestern edge facing eastward. Vegetation on northern cut-slope is sparse and may need to be revegetated if it is not increasing.



Photo 5. View of area in the southern portion of the project area where it appears stormwater has breached the stormwater berm. This area needs to be stabilized.



Photo 6. View of cobble run-down in the southwestern portion of the project area.