

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
12/23/2016  
Submitted Date:  
12/27/2016  
Document Number:  
681700251

**FIELD INSPECTION FORM**

Loc ID 320511 Inspector Name: Arauza, Steven On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
OGCC Operator Number: 46290  
Name of Operator: K P KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**  
12 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>
Canfield, Chris		chris.canfield@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272178	WELL	PR	04/20/2005	GW	001-09507	STANDLEY 2-2	EI
272179	WELL	PR	04/20/2005	GW	001-09506	STANDLEY 1-2	EI

**General Comment:**  
COGCC Environmental follow-up inspection for Remediation Project #9504 and Spill ID #444779. Checked stream adjacent to location and did not observe offsite sediment transport or any areas of hydrocarbon sheen. LTE is continuing to complete remedial actions described in approved Form 27 Site Investigation and Remediation Workplan (document #400951704) on behalf of Synergy Resources Corporation. A Summary Report was received by the COGCC on 8/17/2016.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Area east of tank battery was rutted.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Pile of unused pea gravel at SW corner of facility (see photos).		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	01/27/2017
Type	OTHER		
Comment:	Possible stained soil observed south of infiltration galleries (see photos).		
Corrective Action:	Remove and properly dispose.	Date:	01/27/2017
Type	OTHER		
Comment:	1" PVC risers from confirmation soil sampling surround facility. Some appear to have been impacted by operations (see photos).		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Pipe fence		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	<a href="#">Chain link</a>		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	<a href="#">Chain link</a>		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Horizontal Separator	# 2		
Comment:	<a href="#">Earthen berm.</a>		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent		Adequate
Comment:	<a href="#">Earthen berm shared with steel crude oil ASTs.</a>			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	268 bbls
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		Adequate
Comment: <a href="#">Earthen berm shared with fiberglass produced water tank.</a>				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 272178 Type: WELL API Number: 001-09507 Status: PR Insp. Status: EIFacility ID: 272179 Type: WELL API Number: 001-09506 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700265	1" PVC riser SE of separators appears to have been impacted by operations	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037985">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037985</a>
681700266	1" PVC riser and damaged cone	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037986">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037986</a>
681700267	pea gravel stockpile	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037987">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037987</a>
681700268	impacted soil south of infiltration galleries.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037988">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037988</a>