

Construction and Stormwater Inspection



Photo 1. Photo taken from the southwest location, facing East. Ditch and berm installed around the entire perimeter of the location. Operator said berms will be further compacted.

Construction and Stormwater Inspection



Photo 2. Photo taken from the southwest location, facing North. Ditch and berm installed around the entire perimeter of the location. Operator said berms will be further compacted.

Construction and Stormwater Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 3. Photo taken from the southeast location, facing North. Ditch and berm installed around the entire perimeter of the location. Operator said berms will be further compacted.

Construction and Stormwater Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 4. Photo taken from the northeast location, facing West. Ditch and berm installed around the entire perimeter of the location. Operator said berms will be further compacted.

Construction and Stormwater Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo 5. Photo taken from the northwest location, facing South. Ditch and berm installed around the entire perimeter of the location. Operator said berms will be further compacted.

Construction and Stormwater Inspection



Photo 6. Photo taken from the western location, facing East towards the topsoil stockpile. Topsoil salvage IN-PROCESS.