

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/20/2016
Submitted Date:
12/28/2016
Document Number:
682401651

FIELD INSPECTION FORM

Loc ID 336504 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445333	WELL	XX	03/31/2016		123-43015	CAMENISCH 10N-34HZ	CI
445334	WELL	XX	03/31/2016		123-43016	CAMENISCH STATE 23N2-34HZ	CI
445335	WELL	XX	03/31/2016		123-43017	CAMENISCH 15N-22HZ	CI
445336	WELL	XX	03/31/2016		123-43018	CAMENISCH 36N-22HZ	CI
445337	WELL	XX	03/31/2016		123-43019	CAMENISCH STATE 23N-34HZ	CI
445338	WELL	XX	03/31/2016		123-43020	CAMENISCH STATE 23N2-34HZ	CI

General Comment:

[This is a construction and stormwater inspection in response to Form 42 Document #401168501- Notice of construction of a new location.](#)

Location Construction

Location ID: 336504 CDP: _____

Comment: Topsoil salvage IN-PROCESS. Topsoil needs to be stabilized and protected from degradation due to wind and water erosion. BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
BERMS	Yes		

Comments: Erosion BMPs: Operator said berms will be further compacted to control stormwater run-on and run-off.

Other BMPs: _____

Corrective Action: _____ Date: _____

DITCHES	Yes		

Comments: Erosion BMPs: _____

Other BMPs: _____

Corrective Action: _____ Date: _____

Comment: _____

Corrective Action: _____ **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>445333</u>	Type: <u>WELL</u>	API Number: <u>123-43015</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445334</u>	Type: <u>WELL</u>	API Number: <u>123-43016</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445335</u>	Type: <u>WELL</u>	API Number: <u>123-43017</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445336</u>	Type: <u>WELL</u>	API Number: <u>123-43018</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445337</u>	Type: <u>WELL</u>	API Number: <u>123-43019</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445338</u>	Type: <u>WELL</u>	API Number: <u>123-43020</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

COGCC Comments

Comment	User	Date
Follow up inspection(s) will proceed while construction of location is IN-PROCESS.	binschusc	12/28/2016
Refer to attached inspection photos in Document #682401652.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401652	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4038829