

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/27/2016
Submitted Date:
12/27/2016
Document Number:
675103233

FIELD INSPECTION FORM

Loc ID 314668 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 6301 DEAUVILLE BLVD
City: MIDLAND State: TX Zip: 79706

Findings:
1 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229227	WELL	IJ	04/11/2007	ERIW	103-06317	MCLAUGHLIN, A C 17	WK

General Comment:

Inspected Facilities

Facility ID: 229227 Type: WELL API Number: 103-06317 Status: IJ Insp. Status: WK

Workover

Comment: AESC rig #2
Tubing/packer leak found
Packer set @ 6545' performed casing pressure test - pressure held/good test
Run casing log to verify casing in good shape - pending casing log results replace packers and tubing and put well back on injection.

Corrective Action:

Date: