



Photo 1. View of the project area from the southern corner facing center.



Photo 2. View of the project area from the southeastern portion of the project area facing northeastward.





Photo 3. View of the southern portion of the project area from the southern corner facing westward.





Photo 4. View of area in the southeastern portion of the project area where erosional channels and tunneling have been repaired.





Photo 5. View diversion ditches recently maintained in the southern portion of the project area.





Photo 6. View of cobble armouring installed around the culvert near the entrance of the project area.





Photo 7. View of area along the western edge of the project area where wattles have failed and additional stormwater controls are needed.





Photo 8. View of newly installed silt trap in the northern portion of the project area. Overflow and a portion of diversion channel are lined with cobble.