

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/13/2016
Submitted Date:
12/29/2016
Document Number:
680601210

FIELD INSPECTION FORM

Loc ID 312010 Inspector Name: ROY, CATHERINE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76104
Name of Operator: SAMSON RESOURCES COMPANY
Address: TWO WEST SECOND ST
City: TULSA State: OK Zip: 74103

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Blanchard, Johnna	970-884-5085	jblanchard@samson.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271430	WELL	PR	12/16/2014	GW	067-08926	GORE GAS UNIT A 15 2	RI
284754	WELL	PR	02/01/2012	GW	067-09165	GORE GAS UNIT A 15-3	RI

General Comment:

This is a followup inspection for inspection number 680600695 conducted on March 2, 2016.

Inspected Facilities

Facility ID: 271430 Type: WELL API Number: 067-08926 Status: PR Insp. Status: RI

Facility ID: 284754 Type: WELL API Number: 067-09165 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Revegetation is progressing within the interim reclamation areas.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater controls have been maintained and new controls installed in areas where erosion was documented. These largely appear to be functioning. However, wattles have failed and do not appear sufficient to control surface flows along a section where the interim reclamation area borders a gully on the western edge of the well pad. See attached photos.

Corrective Action: Additional erosion controls are needed to stabilize the section along the western edge of the project area where stormwater flows continue to erode the bank of a gully. A new corrective action date is assigned to account for the previous corrective action request that was sufficiently responded to. The date is extended to accomodate likely snow conditions or frozen soils during the winter months.

Date: 05/01/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601212	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4040401