

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/27/2016

Submitted Date:

12/27/2016

Document Number:

675103233**FIELD INSPECTION FORM**

Loc ID 314668 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229227	WELL	IJ	04/11/2007	ERIW	103-06317	MCLAUGHLIN, A C 17	WK

**General Comment:**

**Inspected Facilities**Facility ID: 229227 Type: WELL API Number: 103-06317 Status: IJ Insp. Status: WK**Workover**

Comment: AESC rig #2  
Tubing/packer leak found  
Packer set @ 6545' performed casing pressure test - pressure held/good test  
Run casing log to verify casing in good shape - pending casing log results replace  
packers and tubing and put well back on injection.

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675103233	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4039119">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4039119</a>