

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
12/27/2016  
Submitted Date:  
12/27/2016  
Document Number:  
675103233

**FIELD INSPECTION FORM**

Loc ID 314668 Inspector Name: GRANAHAN, KYLE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 6301 DEAUVILLE BLVD  
City: MIDLAND State: TX Zip: 79706

**Findings:**

1 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229227	WELL	IJ	04/11/2007	ERIW	103-06317	MCLAUGHLIN, A C 17	WK

**General Comment:**

**Inspected Facilities**

Facility ID: 229227 Type: WELL API Number: 103-06317 Status: IJ Insp. Status: WK

**Workover**

Comment: AESC rig #2  
 Tubing/packer leak found  
 Packer set @ 6545' performed casing pressure test - pressure held/good test  
 Run casing log to verify casing in good shape - pending casing log results replace packers and tubing and put well back on injection.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675103233	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4043308">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4043308</a>