

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/23/2016
Submitted Date:
01/03/2017
Document Number:
681700270

FIELD INSPECTION FORM

Loc ID 319867 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10311
Name of Operator: SYNERGY RESOURCES CORPORATION
Address: 20203 HIGHWAY 60
City: PLATTEVILLE State: CO Zip: 80651

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Pennington, David		dpennington@syrginfo.com	All Inspections
Brian, Jerry		jbrian@syrginfo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445747	SPILL OR RELEASE	CL	04/05/2016		-	SPILL/RELEASE POINT	EI

General Comment:

COGCC Environmental follow-up inspection for Remediation Project #9613 (Spill ID #445747). Installation of AS/SVE system and shed is progressing as described in approved Site Investigation and Remediation Workplan. Five (5) 55 gallon drums of investigation-related soil cuttings are being stored on-location and are awaiting disposal. Observations and corrective actions were initially filed under inspection report #681700250 and were separated into this report in response to FIRR filed by facility operator.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 445747 Type: SPILL OR API Number: - Status: CL Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700270	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4043404
681700274	AS/SVE system shed installed on location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4043043
681700275	AS/SVE wells are being installed, piping from wells to shed awaiting burial.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4043044
681700276	Soil cuttings related to investigation are stored in 55 gallon drums awaiting disposal.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4043045