

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2017

Submitted Date:

01/06/2017

Document Number:

674901415

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
325858 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10254  
 Name of Operator: RED MESA HOLDINGS/O&G LLC  
 Address: 5619 DTC PARKWAY - STE 800  
 City: GREENWOOD State: CO Zip: 80111

**Findings:**

- 9 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
St John, William (Cal)		cal.stjohn@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Weems, Mark		mark.weems@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215480	WELL	PR	01/05/2009	OW	067-07085	TALBOT-WIDEMAN 13-1	EI

**General Comment:**

On January 6, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Red Mesa Holdings LLC Talbot-Wideman #13-1. This field inspection resulted from complaint #200440902. For the most recent field inspection report of this facility, please refer to document #668402746, which includes an attached FLIR camera video of the well head. During this site visit, it was observed that conditions at this location were similar to the photos attached to inspection document #674601624 conducted on 3/26/15. The location was snow covered during this field inspection.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Location sign mounted to guard fencing for pump jack.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Unlabeled propane tank on east side of location.		
Corrective Action:	Install sign to comply with Rule 210.d. Corrective action date taken from inspection document #674601624.	Date:	05/04/2015

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Disconnected propane tank on east side of location.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details. Corrective action date taken from inspection document #674601624.	Date:	05/04/2015

Overall Good:

**Spills:**

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	PUMP JACK		
Comment:	Guard fencing present.		
Corrective Action:		Date:	

**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Stained soils beneath prime mover.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Corrective action date taken from inspection document #674601624.	Date:	05/04/2015

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	100 BBLS	STEEL AST		37.102771,-108.104006
Comment:	Label and placard are peeling off of tank. 100 bbl. AST is labeled "WNR-11709 11-10 3/4 0-11 3/4".				
Corrective Action:				Date:	

<b>Paint</b>				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 215480 Type: WELL API Number: 067-07085 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Spill Response	Pass	Spill kit near AST.

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On January 6, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Red Mesa Holdings LLC Talbot-Wideman #13-1. This field inspection resulted from complaint #200440902. For the most recent field inspection report of this facility, please refer to document #668402746, which includes an attached FLIR camera video of the well head. During this site visit, it was observed that conditions at this location were similar to the photos attached to inspection document #674601624 conducted on 3/26/15. The location was snow covered during this field inspection. Stained soils, noted in inspection document #674601624, were present beneath the prime mover during this field inspection. An unused propane tank, noted on previous inspections, is present on the east side of the location. The label and placard on the 100 bbl. AST is peeling off of the tank.</p>	hughesj	01/06/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901416	Talbot-Wideman #13-1 pump jack.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046050">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046050</a>
674901417	Stained soil beneath prime mover.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046051">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046051</a>
674901418	Talbot-Wideman #13-1 well head.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046052">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046052</a>
674901419	Unused propane tank on east side of location.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046053">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046053</a>
674901420	100 bbl. AST.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046054">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046054</a>