

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2017

Submitted Date:

01/03/2017

Document Number:

674004732**FIELD INSPECTION FORM**

Loc ID 336289 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289815	WELL	PR	05/23/2010	OW	123-24922	CARMA 12-35	PR
289816	WELL	PR	08/02/2011	OW	123-24921	CARMA 11-35	PR
290566	WELL	PR	02/07/2014	OW	123-25140	CARMA 32-35	PR
290677	WELL	PR	03/12/2014	GW	123-25188	CARMA 22-35	PR
435524	WELL	PR	03/11/2015	OW	123-38631	BAREFOOT STATE 9C-36HZ	PR
435525	WELL	PR	03/09/2015	OW	123-38632	BAREFOOT STATE 40N-36HZ	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Metal Pickey		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Metal Picket		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	See inspection document number 674002405 for details				

Corrective Action:				Date:	
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type	Ignitor/Combustor				
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	289815	Type:	WELL	API Number:	123-24922	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
BradenHead									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			
Facility ID:	289816	Type:	WELL	API Number:	123-24921	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
BradenHead									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			
Facility ID:	290566	Type:	WELL	API Number:	123-25140	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
BradenHead									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			
Facility ID:	290677	Type:	WELL	API Number:	123-25188	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
BradenHead									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			
Facility ID:	435524	Type:	WELL	API Number:	123-38631	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

BradenHead			
Comment: Bradenhead plumbed to surface.		Date: _____	
Corrective Action: _____		Date: _____	

Facility ID: 435525	Type: WELL	API Number: 123-38632	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment: PR		Date: _____	
Corrective Action: _____		Date: _____	

BradenHead			
Comment: Bradenhead plumbed to surface.		Date: _____	
Corrective Action: _____		Date: _____	

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Calm Speed: _____ (mph) Direction From: _____ Weather: Cloudy Temperature: 25 (F)Assisting Staff: Jeff Rickard Camera #: _____☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
10:30	AM	11:30	AM	Wellhead(s)

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Routine inspection. FLIR Video of API 05-123-25140 attached.	carlilec	01/03/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674004732	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4044302
674004733	Normal Video of Well ID	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4043022
674004734	FLIR Video of Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4043023