

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2017

Submitted Date:

01/04/2017

Document Number:

685501680**FIELD INSPECTION FORM**
 Loc ID 318937 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|--------------|-------------------------|---------------------------------|
| OLSON, JUSTIN | 303-910-4717 | justin.olson@hrmres.com | engineering |
| Pape, Terry | 303-893-6621 | tpape@hrmres.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 242540 | WELL | PR | 03/15/2004 | GW | 123-10331 | LORI STATE 31-36 | PR |

General Comment:

Location**Lease Road:**

| | | | |
|-------------------|------|-------|--|
| Type | Main | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----|-------|--|
| Comment: | OK | | |
| Corrective Action: | | Date: | |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 242540 Type: WELL API Number: 123-10331 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

BradenHeadComment: BRADENHEAD PLUMBED TO SURFACE

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

INTERMITTER CONTROLLER ON WELLHEAD
 BERMS IN PROCESS OF BEING REBUILT WORK HAS STARTED, I WILL RE-INSPECT
 THIS LOCATION WHEN WORK IS COMPLETE

montoyaj

01/04/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 685501680 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4044403 |