

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
01/11/2017  
Submitted Date:  
01/11/2017  
Document Number:  
674901426

**FIELD INSPECTION FORM**

Loc ID 325858 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10254  
Name of Operator: RED MESA HOLDINGS/O&G LLC  
Address: 5619 DTC PARKWAY - STE 800  
City: GREENWOOD State: CO Zip: 80111

**Findings:**

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Weems, Mark		mark.weems@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215480	WELL	PR	01/05/2009	OW	067-07085	TALBOT-WIDEMAN 13-1	EI

**General Comment:**

On January 11, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Red Mesa Holdings, LLC Talbot-Wideman #13-1. COGCC SW Regional Engineer Mark Weems was on site during this field inspection. The purpose of this site visit was to expose the Bradenhead valve in preparation for performing a Bradenhead test. For the most recent field inspection report of this facility, please refer to document #674901415.

Location						
Overall Good: <input checked="" type="checkbox"/>						
<b>Signs/Marker:</b>						
Type	OTHER					
Comment:	Unlabeled propane tank on east side of location.					
Corrective Action:	Install sign to comply with Rule 210.d. Corrective action date taken from inspection document #674601624.				Date:	05/04/2015
Type	WELLHEAD					
Comment:	Location sign mounted to guard fencing for pump jack.					
Corrective Action:					Date:	
<b>Emergency Contact Number:</b>						
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>
<b>Good Housekeeping:</b>						
Type	UNUSED EQUIPMENT					
Comment:	Disconnected propane tank on east side of location.					
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details. Corrective action date taken from inspection document #674601624.				Date:	
Overall Good: <input type="checkbox"/>						
<b>Spills:</b>						
Type	Area	Volume				
In Containment: No						
Comment:	<input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?						
<b>Fencing/:</b>						
Type	PUMP JACK					
Comment:	Guard fencing present.					
Corrective Action:					Date:	
<b>Equipment:</b>						
					corrective date	
Type: Deadman # & Marked	# 4					
Comment:						
Corrective Action:					Date:	
Type: Pump Jack	# 1					
Comment:	Stained soil beneath prime mover.					
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Corrective action date taken from inspection document #674601624.				Date:	05/04/2015
<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	100 BBLS	STEEL AST		37.102771,-108.104006	
Comment:	Label and placard are peeling off of tank. 100 bbl. AST is labeled "WNR-11709 11-10 3/4 0-11 3/4".					
Corrective Action:					Date:	

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			
		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			
		Date:	

**Inspected Facilities**

Facility ID: 215480 Type: WELL API Number: 067-07085 Status: PR Insp. Status: EI

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Spill Response	Pass	Spill kit near AST.

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

### COGCC Comments

Comment	User	Date
<p>On January 11, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Red Mesa Holdings, LLC Talbot-Wideman #13-1. COGCC SW Regional Engineer Mark Weems was on site during this field inspection. The purpose of this site visit was to expose the Bradenhead valve in preparation for performing a Bradenhead test. For the most recent field inspection report of this facility, please refer to document #674901415. The intermediate casing valve and the Bradenhead valve were excavated during this site visit.</p>	hughesj	01/11/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901427	Talbot-Wideman #13-1 well head.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4049513">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4049513</a>
674901428	Bradenhead valve exposed.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4049514">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4049514</a>
674901429	Surface and intermediate casing valves.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4049515">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4049515</a>
674901430	Excavated well head with valves exposed.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4049516">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4049516</a>